

Date: Thursday, 11/24/2005 12:06:32 PM
 User: Linda Lacelle

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: 350/212/130 BASKET LID
Job Number	: 24964B		
Estimate Number	: 10193		
P.O. Number	: N/A	Part Number	: D2512
This Issue	: 11/24/2005	S.O. No.	: N/A
Prsht Rev.	: NC	Drawing Number	: D2512 REV D1
First Issue	: N/A	Project Number	: N/A
Previous Run	: 24836A	Drawing Revision	: D1
	Type : LARGE FAB ASSY	Material	: N/A
Written By	: <u>SEE COMMENT BELOW</u>	Due Date	: 1/15/2006
Checked & Approved By	: <u>SEE COMMENT BELOW</u>	Qty:	1
Comment	: Rev Est:M 03.01.31 Added D2012-117 for D130-701-041 KJ/ RF	Um:	Each

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	M304TS0750W065	304 SQ Tube.75x.75x.065W
-----	----------------	--------------------------



Comment: Qty.: 30.4931 f(s)/Unit Total : 30.4931 f(s)

Pick:

3/4"x3/4" 304/316 SS tube .063" wall

Batch: M19447

AA 06/04/13

2.0	D31663	Basket Hoop
-----	--------	-------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
1	D3166-3	Basket Hoop	<u>B24546</u>

AA 06/04/13

3.0	D2506	Placard
-----	-------	---------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
1	D2506	Label Plate	<u>B23563</u>

AA 06/04/13

4.0	D23271	Spacer Bushing
-----	--------	----------------



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
2	D2327-1	Bushing	<u>B24873</u>

AA 06/01/13

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 11/24/2005 12:06:33 PM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 350/212/130 BASKET LID

Job Number: 24964B

Part Number: D2512

Job Number:



Seq. #: Machine Or Operation: Description :

5.0 D22321 Hinge



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
2	D2232-1	Hinge plate	<u>B23445</u>

AA 06/01/13

6.0 D2581 Mounting Bracket



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
2	D2581	Mounting Bracket	<u>B23584</u>

AA 06/01/13

7.0 M304EX07516F Expanded Metal Flat Stai



Comment: Qty.: 18.0000 sf(s)/Unit Total : 18.0000 sf(s)

Pick:

Qty	Part Number	Description	Batch
18 sf	M304EX0.75-16F	Expanded Metal	<u>M19149</u>

AA 06/01/17

8.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Cut 3/4" x 3/4" square tubing as per Dwg D2512

2-Cut (4) D2236 From D3166-3

3-Drill holes in D2512-1 as per Dwg D2512 using Drill Jig DT8305

4-D2012-117 is included in D3172-041 EC130 Basket Base BOM.
EC130 Basket only

Pick:

Qty	Part Number	Description	Batch
2	D2012-117	Clevis	

AA 06/01/17

5-Weld as per Dwg D2512 using Welding Table and corner Jig Deburr as required

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 11/24/2005 12:06:33 PM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 350/212/130 BASKET LID

Job Number: 24964B

Part Number: D2512

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

9.0	QC9/6	DDIMENSIONAL & WELDING INSPECTION
-----	-------	-----------------------------------



Comment: DDIMENSIONAL & WELDING INSPECTION

PD 0601-17

10.0	POWDER COATING	POWDER COATING
------	----------------	----------------



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

FC 0601 17

11.0	HAND FINISHING1	HAND FINISHING RESOURCE #1
------	-----------------	----------------------------



Comment: HAND FINISHING RESOURCE #1

Wing Walk and Spray Paint black as per Dwg D2512 and QSI 005 4.4

Spray: m19279

Batch: m18276

FC 0601 18

12.0	QC3	INSPECT POWDER COAT/CHEMICAL CONVERSION
------	-----	-----------------------------------------



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

m 06 01 18

Job Completion



LEVEL 21 INSPECTION DEP 0601/19

u 06-01-19

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries